

Redmine - Defect #9645

Marques d'unité intérieure split

2011-11-23 14:26 - Arnaud Toumeyragues

Status: Closed	Start date: 2011-11-23
Priority: Low	Due date:
Assignee:	% Done: 0%
Category:	Estimated time: 0.00 hour
Target version:	Affected version:
Resolution: Invalid	
Description Les marques d'unité intérieure split ne correspondent à celles des unités extérieures. Elles correspondent davantage aux fabricants de chaudière.	

History

#1 - 2011-11-23 17:53 - Etienne Massip

- Status changed from New to Closed
- Resolution set to Invalid